

消 防 處
牌 照 及 審 批 總 區
香 港 九 龍 尖 沙 咀 東 康 莊 道 1 號 5 樓
消 防 總 部 大 廈



**FIRE SERVICES DEPARTMENT
LICENSING AND CERTIFICATION
COMMAND**

FIRE SERVICES HEADQUARTERS BUILDING,
No.1 Hong Chong Road, 5/F,
Tsim Sha Tsui East Kowloon,
Hong Kong.

本處檔號 OUR REF.: (14) in FP 206/0512 II
來函檔號 YOUR REF.: FSD/FS.27741/TKC/jh
電報掛號 TELEX:39607 HKFSD HX
電子郵件 E-mail <lcplc2@hkfsd.gov.hk>
圖文傳真 FAX: 852-2723 2197
電 話 TEL NO.: 2733 7744

RECEIVED
THORN SECURITY (H.K.) LTD

23 SEP 2002

16 September 2002

Thorn Security (Hong Kong) Ltd.
12/F, Kornhill Metro Tower,
No.1 Kornhill Road, Quarry Bay,
Hong Kong.

Dear Sirs,

Acceptance of Detector

I refer to my interim reply of 8.8.2002 on the captioned subject.

The proposed use of the following detectors, which were certificated by the Underwriters Laboratories Inc. (UL), is considered acceptable to this Department:-


Manufacturer	Firefighting Enterprises Ltd.
Type	Projected beam smoke detector
Model	50R and 100R
Testing Standard	UL Standard 268 (Fourth Edition)
Supporting Document	Test Report File S3417 Project 01NK32703 issued by UL on 27.12.2001.

/P.2

Please note that the above acceptance is subject to :-

- i. all conditions as stipulated in the above-mentioned test report being complied with;
- ii. the installation conforming to FSD Circular Letter No. 1/2002 Rules for Fire Detection and Alarm Systems for Buildings; and
- iii. the components used in the installation being compatible.

Yours faithfully,

A handwritten signature in black ink, appearing to be 'LAU Kwai-shan', written in a cursive style.

(LAU Kwai-shan)
for Director of Fire Services

LKS/RL/lkc